

FIG. 3  
(PRIOR ART)






FIG. 4 (PRIOR ART)






FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11





FIG. 12A

FIG. 12B






FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17






FIG. 18




FIG. 19




FIG. 20




FIG. 22A




FIG. 22B




FIG. 21




FIG. 24




FIG. 23





FIG. 25




FIG. 26









FIG. 27








FIG. 30

Preventing of negative pressure









FIG. 31






FIG. 34